

1832

Subject: Inspection of elevator spar

Applies to: SAAB-SAFIR 91B, 91B2, 91C, and 91D

Reason: Damage to elevator spar at bearing assembly attachment has been reported in a few cases

Required action: Carry out the required action in accordance with SAAB-SCANIA Service Bulletin
No 91.1.004, Issue 2

Date: 1982-09-27

Time of compliance: Before further flight, if not already performed. Thereafter at intervals not exceeding
200 flight hours.