



## **SWEDISH AIRWORTHINESS DIRECTIVES**

### **Section 1. Swedish Manufactured Aeronautical Products**

AIRWORTHINESS DIRECTIVE NO: 1-017

AIRCRAFT TYPE: SAAB SAFIR 91B, 91B-2, 91C and 91D

SUBJECT: Periodical inspection of fuel hand-pump actuating system

BACKGROUND: It has been reported that the cable assembly of the manually actuated fuel pump has failed during operation in an emergency situation.

REFERENCE DOCUMENTS: SAAB-SCANIA SB No 91.4.003, Norwegian LDP 44/85 and BCA letter L 2373/85-1202 dated 86-01-02

ACTIONS: Check the cable assembly, return spring and segment in accordance with SB No 91.4.003

COMPLIANCE TIME: Within 50 flight hours after the effective date of this SAD, unless previously accomplished, and thereafter every 100-hours inspection.

EFFECTIVE DATE OF ISSUE: March 19, 1986

LFS: 1986:16

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.

Norrköping 1986-03-19

Board of Civil Aviation  
Flight Safety Department