



service bulletin

Date: July 1961

No. 91.2.005

AIRCRAFT SAAB 91B, 91B-2, 91C AND 91D WITH MODIFICATION BULLETIN 91.2/10 INTRODUCED OR WITH MANUFACTURING No. 91.310, 91.346 - 91.432 AND 91.439.

SUBJECT: Replacement of straight oil nipple with elbow oil nipple at upper torsion link bolt of nose gear.

REASON: The accessibility for lubrication with standard grease guns of the oil nipple at upper torsion link of nose gear is restricted. The necessity of using special equipment can be avoided simply by introduction of an elbow oil nipple.

TIME OF COMPLIANCE: At owner's discretion.

PARTS AFFECTED: Oil nipple AS 254501-1 at UPPER torsion link bolt of nose gear, cf Modification Bulletin 91.2/10 fig. 1 item 06 or Spare Parts Catalogue 91C and 91D 91.2505/01 item 21a.

WORK PROCEDURE: Screw away the above mentioned oil nipple and replace it with a 90-degree elbow oil nipple AS 254501-4 or equivalent.

NOTE: Aircraft with Manuf. Nos. above 91.432 will have this elbow nipple fitted during manufacturing. (Except aircraft No. 91.439.)