



# MODIFICATION BULLETIN

AIRPL  
MODEL

91.8/1

91

PAGE 1 OF 1

Radio, Replacement of antenna mast

URGENCY: III

EFFECT ON WEIGHT DISTRIBUTION:

TIME OF DELIVERY  
FOR NECESSARY PARTS: 29th Nov. 1947

WEIGHT CHANGE  
LBS.

STATION  
IN.

MOMENT CHANGE  
LBSIN.

Saab/C

-

-

-

MARKING: None

Drawings: Not essential

507803 Radio

Parts required on each plane:-

1 Antenna Mast SA 590566 Steel

Following parts on each plane are obsolete

1 Antenna Mast SA 590566 Aluminium (Scrap)

Aircraft concerned:-

91104-91110, 91115

(Number of aircraft: 8)

Spare Parts not involved.

It has occurred in flight that oscillation of the antenna mast has caused the antenna to break off. For this reason the aluminium antenna mast should be replaced by a steel mast in order to eliminate the danger of breaking.

Working procedure:-

Unfasten the antenna from the top of the mast.

Remove the sheet metal strip seal between windshield and antenna mast.

Remove the screws attaching the insulating tube to the lower portion of the mast.

Unfasten the screw, securing the mast to the fuselage and remove the mast.

Mount the new mast with the new insulating tube.

Attach the sheet metal strip and the antenna.

DEC. 1948

SAAB SERVICE DEPT:

*C. Larsson*

SAAB DESIGN DEPT:

*O. Öppling*

ROYAL SWEDISH AERONAUTICS BOARD:

*Stegellhorn*